

INSPECTION REPORT

Name of Work : Development Works for providing Drinking water facility in Bagalgunte ward No.14.

Work Order : No.EE/PD/DZ/WO/03/2015-16 dtd 10/03/16

Agency : KRIDL

B.R.No. & Date : 529/15-16 Date: 29-11-2016

Bill Amount : Rs.21,97,895/-

Job Code : 014-16-000019

P. Code : P3110, 14th Finance grant.

Date of Inspection : 27/12/16.

The above said work "development work for providing drinking water facility in Bagalgunte ward no 14" was shown to me by the concerned ward Engineer. The above said work is inspected by me along with the ward Engineer.

The work done is satisfactory.

[Signature]
N. 1/10/16

[Signature]
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ಪಾಸರಹಳ್ಳಿ, ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ದಿ. 27/12/16
ಬೆಂಗಳೂರು

[Signature]
MANJUNATH. K
DOM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

INSPECTION REPORT

Name of Work : Development Works for providing Drinking water facility in Bagalgunte ward No.14.



[Signature]
L14

[Signature]
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಧೀನಾಧಿಕಾರಿ
ಟಿ.ಎಸ್.ಎಸ್.ಎಸ್. ಉಪ-ವಿಭಾಗ
ಜಿಲ್ಲಾಧಿಕಾರಿ, ಬೆಂಗಳೂರು
ಬೆಂಗಳೂರು

[Signature]
MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

INSPECTION REPORT

Name of Work : Development Works for providing Drinking water facility in Bagalgunte ward No.14.



[Handwritten signature]
Wg

[Handwritten signature]
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಟಿ.ರಾಸರಕಲ್ಕ ಉಪ-ವಿಭಾಗ
ಜಾಗಲಗುಂಟೆ, ಬಿಜಿಎಂಪಿ
ಬೆಂಗಳೂರು

[Handwritten signature]
MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT